

AD-A088 796

KIMBALL (L ROBERT) AND ASSOCIATES EBENSBURG PA  
NATIONAL DAM INSPECTION PROGRAM. HIDDEN LAKE DAM. (NOS ID NUMBE--ETC(U)  
JUL 80

F/6 13/13

DACW31-80-C-0020


NL

UNCLASSIFIED


[OF]  
AD  
ACW31-80-C-0020



END  
DATE  
FILMED  
10-80  
DTIC



LEVEL



AD A088796



This document has been approved  
for public release and sale; its  
distribution is unlimited.

ORIGINAL CONTAINS COLOR PLATES: ALL DDC  
REPRODUCTIONS WILL BE IN BLACK AND WHITE

(1)  
SUSQUEHANNA RIVER BASIN  
HIDDEN LAKE OUTLET, LUZERNE COUNTY,

PENNSYLVANIA


**HIDDEN LAKE DAM**

(NDS-ID-PA-1136)

DER-ID-40-228

**SHERMAN HOOVER**

**PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**



11 Jul 80

12/69

15 DMS-31-80-C-00001

Prepared By

**L. ROBERT KIMBALL & ASSOCIATES**  
CONSULTING ENGINEERS & ARCHITECTS  
EBENSBURG, PENNSYLVANIA  
15931

FOR

**DEPARTMENT OF THE ARMY**  
**BALTIMORE DISTRICT CORPS OF ENGINEERS**  
BALTIMORE, MARYLAND  
21203

JULY, 1980

This document has been approved  
for public release and sale; its  
distribution is unlimited.

411 059

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I REPORT  
NATIONAL DAM INSPECTION REPORT

NAME OF DAM	Hidden Lake Dam
STATE LOCATED	Pennsylvania
COUNTY LOCATED	Luzerne
STREAM	Unnamed tributary to Shickshinny Lake
DATE OF INSPECTION	April 10, May 21, 1980

ASSESSMENT

The assessment of Hidden Lake Dam is based upon visual observations made at the time of inspection, hydraulic and hydrologic computations and past operational performance.

The Hidden Lake Dam appears to be in poor condition. A slide was noted on the downstream slope approximately 240 feet from the left abutment. The slide appeared to be inactive. A wet area was noted to the left of the discharge end of the 15" corrugated metal pipe drainline. Flow from the seepage area was determined to be less than 1 gallon per minute. The drainline for the dam consists of a 15" corrugated metal pipe with the upstream portion of the pipe blocked. No adequate facilities exist to regulate the reservoir level.

The Hidden Lake Dam is a high hazard-small size dam. The recommended spillway design flood (SDF) for this dam is the 1/2 PMF to PMF. Based on the downstream potential for loss of life, the spillway design flood has been selected as the PMF. The spillway and reservoir are capable of controlling approximately 1% of the PMF without overtopping the embankment (low spot). Based on criteria established by the Corps of Engineers, the spillway is termed seriously inadequate. If Hidden Lake Dam would fail due to overtopping, the hazard potential for loss of life and property damage immediately downstream of the dam would be significantly increased from that which would exist just prior to the overtopping. Hidden Lake Dam is classified as an unsafe non-emergency dam.

The following recommendations and remedial measures should be instituted immediately.

1. A warning system should be developed to warn downstream residents of large spillway discharges or imminent failure of the dam.
2. A detailed hydrologic and hydraulic analysis should be conducted by a registered professional engineer knowledgeable in dam design and construction to increase the spillway capacity of the dam. The recommendations resulting from the study should be implemented immediately.

HIDDEN LAKE DAM  
PA 1136

3. A detailed stability analysis should be conducted by a registered professional engineer knowledgeable in dam design and construction. An analysis should include the monitoring and evaluation of the wet area located at the toe of the dam near the outlet for the 15 inch corrugated metal pipe. The slide should be investigated and repaired as required upon completion of the stability analysis.

4. Debris collecting in the spillway and spillway approach should be cleared and continue to be cleared as required.

5. Small trees and brush existing on the downstream slope should be removed under the direction of a registered professional engineer knowledgeable in dam design and construction.

6. Re-evaluate upstream closure for the 15 inch corrugated metal pipe drainline.

7. Regular safety inspections should be conducted in accordance with provisions stipulated by the Commonwealth of Pennsylvania regarding the inspection of dams.

SUBMITTED BY:

L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS AND ARCHITECTS

Date

R. Jeffrey Kimball, P.E.

APPROVED BY:

Date

15 August 80  
JAMES W. PECK  
Colonel, Corps of Engineers  
District Engineer

Accession For	
NTIS	GW&I
DOC TAB	
Unannounced	
Justification	
By	
Distribution	
Availability	
Dist	Available for special
A	



Overview of Hidden Lake Dam



## TABLE OF CONTENTS

	PAGE
SECTION 1 - PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	5
2.1 Design	5
2.2 Construction	5
2.3 Operation	5
2.4 Evaluation	5
SECTION 3 - VISUAL INSPECTION	6
3.1 Findings	6
3.2 Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES	8
4.1 Procedures	8
4.2 Maintenance of Dam	8
4.3 Maintenance of Operating Facilities	8
4.4 Warning System in Effect	8
4.5 Evaluation	8
SECTION 5 - HYDRAULICS AND HYDROLOGY	9
5.1 Evaluation of Features	9
5.2 Evaluation Assumptions	9
5.3 Summary of Overtopping analysis	9
5.4 Summary of Dam Breach Analysis	10
SECTION 6 - STRUCTURAL STABILITY	11
6.1 Evaluation of Structural Stability	11
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES	12
7.1 Dam Assessment	12
7.2 Recommendations/Remedial Measures	12

## APPENDICES

- APPENDIX A - CHECKLIST, VISUAL INSPECTION, PHASE I
- APPENDIX B - CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION,  
OPERATION, PHASE I
- APPENDIX C - PHOTOGRAPHS
- APPENDIX D - HYDROLOGY AND HYDRAULICS
- APPENDIX E - DRAWINGS
- APPENDIX F - GEOLOGY

PHASE I  
NATIONAL DAM INSPECTION PROGRAM  
HIDDEN LAKE DAM  
NDI. I.D. NO. PA 1136  
DER I.D. NO. 40-228

SECTION 1  
PROJECT INFORMATION

1.1 General.

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose. The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Hidden Lake Dam is an earthfill dam, 550 feet long and 20 feet high. The crest width of the dam is 15 feet. The visible portion of the upstream slope was measured to be 1H:1V and the downstream slope was measured to be 1.5H:1V. No riprap protection was observed on the upstream slope.

The spillway is located at the right abutment and consists of an overflow section 35 feet in length. The spillway overflow section is cut into shale and flow through this section discharges beyond the toe of the dam. Flow from Hidden Lake Dam discharges to a natural stream which ultimately enters into Shickshinny Lake approximately 2000 feet downstream.

The drainline for this dam consists of a 15 inch CMP which outlets at the toe. The drainline is located approximately 220 feet from the left abutment. The drainline is not equipped with a control. The upstream end of the pipe is equipped with a section of terra-cotta pipe that is blocked with a concrete plug. The blocked section of the pipe is marked at the surface of the reservoir by a buoy which is attached by a cable to the terra-cotta pipe. The owner reported that if the need should arise to drain the lake that a weighted object could be lowered along the cable down to the terra-cotta pipe, and the pipe could be smashed by the weight thus allowing the lake to drain.

b. Location. The dam is located on unnamed tributary to Shickshinny Lake, Luzerne County, Pennsylvania. Hidden Lake Dam can be located on the Shickshinny, U.S.G.S. 7.5 minute quadrangle.

c. Size Classification. Hidden Lake Dam is a small size dam (20 feet high, 87 ac-ft).

d. Hazard Classification. Hidden Lake Dam is classified as a high hazard dam. Downstream conditions indicate that loss of more than a few lives is probable should the structure fail. One home is located approximately 1000 feet (4 people) downstream of Hidden Lake Dam. Shickshinny Lake is located approximately 1/2 miles downstream and the Borough of Shickshinny is located 4 1/2 miles downstream.

e. Ownership. Hidden Lake Dam is owned by Mr. Sherman Hoover. Correspondence should be addressed to:

Mr. Sherman Hoover  
R.D. 1  
Shickshinny, Pennsylvania 15865  
(717) 256-3437

f. Purpose of Dam. Hidden Lake Dam was constructed for the purpose of recreation.

g. Design and Construction History. Hidden Lake Dam was built in 1967 by the Laubach Construction Company. There was no engineer retained for the design or analysis of the dam. The owner reported that during construction the approach to the upstream slope was dozed to a 3H:1V slope. The slope near the top of the dam which was observed during the inspection was somewhat steeper than that reported by the owner. No design drawings were available and construction information was supplied by the owner. The owner supplied the inspection team with a contour map which was made prior to construction of the dam. This map was utilized during the hydrologic and hydraulic analysis for this dam.

h. Normal Operating Procedures. No regularly scheduled operations are conducted at the dam. Debris which collects in the spillway is cleared on a regular basis.

### 1.3 Pertinent Data.

- |  |  |
|--|--|
| a. <u>Drainage Area.</u>               | 0.36 square miles<br>(U.S.G.S. 7.5<br>minute quadrangle) |
| b. <u>Discharge at Dam Site (cfs).</u> |  |
| Maximum known flood at dam site        | Unknown  |
| Drainline capacity at normal pool      | Unknown  |
| Spillway capacity at top of dam        | 10 cfs   |

c. Elevation (U.S.G.S. Datum) (feet). - Field survey based on an estimated pool elevation of 1000 feet from U.S.G.S. 7.5 minute quadrangle.

Top of dam - low point	1000.2
Top of dam - design height	Unknown
Normal pool	1000.0
Spillway crest	1000.0
Entrance invert - 15" CMP	Unknown
Exit invert - 15" CMP	980.2
Maximum tailwater	None
Toe of dam	980.0

d. Reservoir (feet).

Length of maximum pool	1600
Length of normal pool	1500

e. Storage (acre-feet).

Normal pool	82
Top of dam	87

f. Reservoir Surface (acres).

Top of dam	16.5
Normal pool	16.5
Spillway crest	16.5

g. Dam.

Type	Earthfill
Length	550 feet
Height	20 feet
Top width	15 feet
Side slopes - upstream	1H:1V to 3H:1V
- downstream	1.5H:1V
Zoning	None
Impervious core	None
Cutoff	None
Grout curtain	None

h. Reservoir Drain.

Type  
Length  
Closure  
Access  
Regulating facilities

15" CMP  
Unknown  
Concrete plug  
None  
None

i. Spillway.

Type  
Crest length  
Crest elevation  
Upstream channel  
Downstream channel

Open cut  
35 feet  
1000.0  
Lake  
Natural stream

## SECTION 2 ENGINEERING DATA

2.1 Design. No design data exists for this dam. The owner supplied a topographic map which was made prior to construction of the dam. This information was utilized in Section 5 of this report. No photographs, permits or correspondence were supplied by PennDER.

2.2 Construction. No information exists on the construction of this dam.

2.3 Operation. No operating records are maintained.

2.4 Evaluation.

a. Availability. Information utilized in the preparation of this report was supplied by the owner. The owner of the dam accompanied the inspection team on the inspection of Hidden Lake Dam.

b. Adequacy. Detailed analysis cannot be made because of a lack of detailed construction information. This Phase I Report is based on available data, visual observations, and a hydrologic and hydraulic analysis. Sufficient information exists to complete a Phase I Report.

SECTION 3  
VISUAL INSPECTION

3.1 Findings.

a. General. The onsite inspection of Hidden Lake Dam was conducted by personnel of L. Robert Kimball and Associates on April 10 and May 2, 1980. The inspection consisted of:

1. Visual inspection of the retaining structure, abutments and toe.
2. Examination of the spillway facilities, exposed portion of any outlet works and other appurtenant works.
3. Observations affecting the runoff potential of the drainage basin.
4. Evaluation of the downstream area hazard potential.

b. Dam. The dam appears to be in poor condition. From a brief survey conducted during the inspection, it was noted that a low spot exists approximately 160 feet from the left abutment. In general, the crest of the dam is slightly lower at mid-embankment and rises slightly to either abutment. Very little of the upstream slope was visible during the inspection. The portion of the upstream slope that was visible during the inspection was measured to be 1H:1V and the downstream slope 1.5H:1V and grass covered. Small trees and brush were observed to be growing on the downstream slope. A slide was observed during the inspection on the downstream slope approximately 240 feet from the left abutment. No seepage was observed in the area of the slide during the inspection. The existence of the slide indicates potential instability of the slope.

c. Appurtenant Structures. The spillway for Hidden Lake Dam is located at the right abutment. The spillway is cut into shale and discharges along the right abutment beyond the toe of the dam.

The drainline for the dam consists of a 15" corrugated metal pipe. The upstream end of the pipe is blocked with a concrete plugged terra-cotta pipe. No regulating valves exist for this pipe. The reservoir can be drained only by smashing the terra-cotta pipe blocking the upstream end of the corrugated metal pipe.

d. Reservoir Area. The watershed is covered by woodlands. The watershed slopes are moderate and do not appear to be susceptible to landslides which would affect the storage volume of the reservoir or overtopping of the dam by displacing water.



e. Downstream Channel. The downstream channel for Hidden Lake Dam consists of a natural unnamed stream which discharges into Shickshinny Lake approximately 2000 feet downstream of Hidden Lake Dam.

3.2 Evaluation. In general, the embankment appears to be in poor condition. Only the outlet for the 15" corrugated metal pipe was visible during the inspection. No other evaluation of the drainline could be made. Minor seepage was observed during the inspection.

SECTION 4  
OPERATIONAL PROCEDURES

4.1 Procedures. The reservoir is maintained at the spillway crest elevation. The spillway and approach is cleared of debris on a regular basis. No other operational procedures are performed at the dam.

4.2 Maintenance of the Dam. No planned maintenance schedule exists. Maintenance of the dam is performed by the owner on an as-need basis. Maintenance of the dam is considered fair.

4.3 Maintenance of Operating Facilities. Maintenance of the spillway is considered fair. Debris is cleared from the spillway on a regular basis by the owner.

4.4 Warning System in Effect. There is no warning system in effect to warn downstream residents of large spillway discharges or imminent failure of the dam.

4.5 Evaluation. Maintenance of the dam is considered fair. There is no system in effect to warn downstream residents of large spillway discharges or imminent failure of the dam, and there is no formal maintenance and inspection program.

SECTION 5  
HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features.

a. Design Data. No calculations or design data pertaining to the hydrology or hydraulics of the dam were available.

b. Experience Data. No rainfall, runoff or reservoir level data were available. The spillway reportedly has functioned adequately in the past.

c. Visual Observations. The spillway appeared to be in fair condition. The spillway is located at the right abutment of the dam and cut into shale. Only 0.2 foot of freeboard exists for this dam.

A low spot was observed on the embankment crest 160 feet from the left abutment.

d. Overtopping Potential. Overtopping potential was investigated through the development of the probable maximum flood (PMF) for the watershed and the subsequent routing of the PMF and fractions of the PMF through the reservoir and spillway.

The Corps of Engineers, Baltimore District, has directed that the HEC-1 Dam Safety Version systemized computer program be utilized. The program was prepared by the Hydrologic Engineering Center (HEC), U.S. Army Corps of Engineers, Davis, California, July, 1978. The major methodologies or key input data for this program are discussed briefly in Appendix D.

5.2 Evaluation Assumptions. To enable us to complete the hydraulic and hydrologic analysis for this structure, it was necessary to make the following assumptions.

1. The pool elevation in the reservoir prior to the storm is the spillway crest elevation 1000.0.

2. Flow through the spillway was considered to exhibit the properties associated with the standard weir flow formula ( $Q=CLH^{1.5}$ ).

3. The top of dam was considered the low spot elevation 1000.2.

5.3 Summary of Overtopping Analysis. Complete summary sheets for the computer output are presented in Appendix D.

Peak inflow (PMF)	1054 cfs
Spillway capacity at top of dam	10 cfs

a. Spillway Adequacy Rating. The Spillway Design Flood (SDF) is based on the hazard and size classification of the dam. The recommended spillway design flood (SDF) for this dam is the 1/2 PMF to PMF. Based on the downstream potential for loss of life and property damage, the spillway design flood has been selected as the PMF. Based on the following definition provided by the Corps of Engineers, the spillway is rated as seriously inadequate as a result of our hydrologic analysis.

Seriously inadequate - High hazard classification dams not capable of passing 50% of the spillway design flood and where there is a significant increase in the hazard potential for loss of life due to overtopping failure.

The spillway and reservoir are capable of controlling approximately 1% of the PMF without overtopping the embankment (low spot).

5.4 Summary of Dam Breach Analysis. As the subject dam cannot satisfactorily pass 50% of the PMF (based on our analysis) it was necessary to perform the dam breach analysis and downstream routing of the flood wave. This analysis determined the degree of increased flooding due to dam failure.

A reservoir pool elevation of 1000.4 was considered as sufficient to cause failure of Hidden Lake Dam. This elevation which represents a depth of overtopping of approximately 2.4 inches was considered sufficient to cause failure because of steep downstream slope at this dam and the visibly erosive nature of the embankment material.

The flood wave was routed downstream with and without failure considerations. The downstream potential for loss of life and property damage is significantly increased by dam failure. The potential for increased flooding downstream is significant, based on our analysis. Therefore, the spillway is rated as seriously inadequate. A detailed printout of the breach analysis is included in Appendix D.

SECTION 6  
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability.

a. Visual Observations. A small slide area was located on the downstream slope approximately 240 feet from the left abutment. The downstream slope of the embankment is grass covered with some small trees and brush on the slope. There is no riprap protection on the upstream face of the embankment. Only minor seepage was observed during the inspection.

The stability of the dam is questionable because of the steep slopes and evidence of past sliding and instability. Based on the lack of information regarding the design and construction of the dam and the observed slides on the downstream slope the structural integrity of the embankment is questionable and should be thoroughly evaluated. No definite determination could be made as to whether the existing slide was active or inactive, however the slide appeared to be inactive.

b. Design and Construction Data. No stability analyses were conducted for this dam. No design drawings were available for review by the inspection team. No construction data is available.

c. Operating Records. No operating records are maintained.

d. Post Construction Changes. No post construction changes were made according to the owner.

e. Seismic Stability. The dam is located in seismic zone 1. No seismic stability analyses has been performed. Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected earthquake loading. Since the static stability of Hidden Lake Dam is questionable it's seismic stability should be assessed during the recommended stability analysis.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The dam appears to be in poor condition. The reservoir is maintained at the spillway crest elevation and very little (less than 3 inches) freeboard exists at the dam. A small slide was observed on the downstream slope. Only minor seepage was observed during the inspection.

The visual observations and hydrologic and hydraulic calculations indicate that the Hidden Lake Dam's spillway is seriously inadequate. The spillway is capable of controlling approximately 1% of the PMF without overtopping the embankment (low spot). The dam breach analysis indicates that a significant increase in the downstream potential for loss of life and property damage exist should the dam fail.

b. Adequacy of Information. Detailed analysis of the dam cannot be made because of the lack of any design or construction data. No design drawings exist for this dam. This Phase I Report is based on visual observations, and hydrologic and hydraulic calculations.

c. Urgency. The recommendations suggested below should be implemented immediately.

d. Necessity for Further Investigation. In order to accomplish some of the recommendations/remedial measures outlined below, further investigations will be required.

7.2 Recommendations/Remedial Measures.

1. A warning system should be developed to warn downstream residents of large spillway discharges or imminent failure of the dam:

2. A detailed hydrologic and hydraulic analysis should be conducted by a registered professional engineer knowledgeable in dam design and construction to increase the spillway capacity of the dam. The recommendations resulting from the study should be implemented immediately.

3. A detailed stability analysis should be conducted by a registered professional engineer knowledgeable in dam design and construction. An analysis should include the monitoring and evaluation of the wet area located at the toe of the dam near the outlet for the 15 inch corrugated metal pipe. The slide should be investigated and repaired as required upon completion of the stability analysis.

4. Debris collecting in the spillway and spillway approach should be cleared and continue to be cleared as required.

5. Small trees and brush existing on the downstream slope should be removed under the direction of a registered professional engineer knowledgeable in dam design and construction.

6. Re-evaluate upstream closure for the 15 inch corrugated metal pipe drainline.

7. Regular safety inspections should be conducted in accordance with provisions stipulated by the Commonwealth of Pennsylvania regarding the inspection of dams.

**APPENDIX A**  
**CHECKLIST, VISUAL INSPECTION, PHASE I**



CHECK LIST  
VISUAL INSPECTION  
PHASE I

NAME OF DAM Hidden Lake Dam COUNTY Luzerne STATE Pennsylvania ID#PA 1136  
 TYPE OF DAM Earthfill HAZARD CATEGORY High  
 DATE(s) INSPECTION April 10, 1980 & May 21, 1980 WEATHER Overcast and cool TEMPERATURE 60°  
 POOL ELEVATION AT TIME OF INSPECTION 1000.0 Est. M.S.L. TAILWATER AT TIME OF INSPECTION None M.S.L.

INSPECTION PERSONNEL:

R. Jeffrey Kimball, P.E. - L. Robert Kimball and Associates  
James T. Hockensmith - L. Robert Kimball and Associates  
O.T. McConnell - L. Robert Kimball and Associates  
Cameron R. Mock - L. Robert Kimball and Associates

James T. Hockensmith  
 \_\_\_\_\_  
 RECORDER

# EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None noted.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Small slide located approximately 240 feet from left abutment.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Some minor erosion on upstream slope.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal alignment appears to be good. Low spot on embankment crest observed near mid-embankment.	
RIPRAP FAILURES	No riprap protection provided at this dam.	

# EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
VEGETATION	Downstream slope. Trees and small brush and sparse grass.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Appears to be good.	
ANY NOTICEABLE SEEPAGE	Wet area observed near outlet of 15" CMP. Seepage less than 1 gpm.	
STAFF GAUGE AND RECORDER	None.	
DRAINS	15" CIP with inlet blocked with a terra-cotta pipe and a concrete plug.	

**CONCRETE/MASONRY DAMS - Not applicable**

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
<b>ANY NOTICEABLE SEEPAGE</b>		
<b>STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS</b>		
<b>DRAINS</b>		
<b>WATER PASSAGES</b>		
<b>FOUNDATION</b>		

**CONCRETE/MASONRY DAMS - Not applicable**

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
<b>SURFACE CRACKS CONCRETE SURFACES</b>		
<b>STRUCTURAL CRACKING</b>		
<b>VERTICAL AND HORIZONTAL ALIGNMENT</b>		
<b>MONOLITH JOINTS</b>		
<b>CONSTRUCTION JOINTS</b>		
<b>STAFF GAUGE OR RECORDER</b>		

OUTLET WORKS - Not applicable

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT		
INTAKE STRUCTURE		
OUTLET STRUCTURE		
OUTLET CHANNEL		
EMERGENCY GATE		

# UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	None. Spillway consists of open earth cut.	
APPROACH CHANNEL	Unrestricted - lake.	
DISCHARGE CHANNEL	Unnamed tributary to Shickshinny Lake.	
BRIDGE AND PIERS	None.	

**GATED SPILLWAY - None**

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
<b>CONCRETE SILL</b>		
<b>APPROACH CHANNEL</b>		
<b>DISCHARGE CHANNEL</b>		
<b>BRIDGE AND PIERS</b>		
<b>GATES AND OPERATION EQUIPMENT</b>		



# DOWNSTREAM CHANNEL


VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Unobstructed unrestricted until past the toe area.	
SLOPES	Moderate to steep, appear to be stable.	
APPROXIMATE NO. OF HOMES AND POPULATION	One home located approximately 1000 feet below the dam. Four people.	

# RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Moderate, appear to be stable.	
SEDIMENTATION	Unknown.	


# INSTRUMENTATION

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER	None.	





# HIDDEN LAKE DAM



PROFILE  
LOOKING UPSTREAM  
Scale: Horiz. 1" = 100'  
Vert. 1" = 20'

APPENDIX B  
CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION, OPERATION,  
PHASE I

**CHECK LIST**  
**ENGINEERING DATA**  
**DESIGN, CONSTRUCTION, OPERATION**  
**PHASE I**

NAME OF DAM Hidden Lake Dam  
 ID# PA 1136

ITEM	REMARKS
AS-BUILT DRAWINGS	None.
REGIONAL VICINITY MAP	U.S.G.S. 7.5 minute quadrangle.
CONSTRUCTION HISTORY	Interview with owner.
TYPICAL SECTIONS OF DAM	None.
OUTLETS - PLAN - DETAILS - CONSTRAINTS - DISCHARGE RATINGS RAINFALL/RESERVOIR RECORDS	None. None. None. None. None.


ITEM	REMARKS
DESIGN REPORTS	None.
GEOLOGY REPORTS	None.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None.
POST-CONSTRUCTION SURVEYS OF DAM	None.
BORROW SOURCES	Site of Impoundment.



ITEM	REMARKS
MONITORING SYSTEMS	None.
MODIFICATIONS	None.
HIGH POOL RECORDS	None.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None.
MAINTENANCE OPERATION RECORDS	None.

ITEM	REMARKS
SPILLWAY PLAN SECTIONS DETAILS	None.
OPERATING EQUIPMENT PLANS & DETAILS	None.

APPENDIX C  
PHOTOGRAPHS



HIDDEN LAKE DAM  
PHOTO INDEX

P-INDICATES PHOTO LOCATION

## HIDDEN LAKE DAM

### Photograph Description

#### Sheet 1. Front


- (1) Upper left - Embankment crest, upstream slope and view of right abutment.
- (2) Upper right - Crest of dam, downstream slope and right abutment.
- (3) Lower left - Crest and downstream slope (note vegetation).
- (4) Lower right - Spillway crest.



#### Sheet 1. Back

- (5) Upper left - Spillway approach.
- (6) Upper right - Downstream slope.
- (7) Lower left - 15" CMP (drainline).
- (8) Lower right - Downstream exposure.

TOP OF PAGE

1	2
3	4





**APPENDIX D**  
**HYDROLOGY AND HYDRAULICS**



APPENDIX D  
HYDROLOGY AND HYDRAULICS

Methodology. The dam overtopping and breach analyses were accomplished using the systemized computer program HEC-1 (Dam Safety Investigation), September, 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. A brief description of the methodology used in the analysis is presented below.

1. Precipitation. The Probable Maximum Precipitation (PMP) is derived and determined from regional charts prepared from past rainfall records including "Hydrometeorological Report No. 40" prepared by the U.S. Weather Bureau.

The index rainfall is reduced from 10% to 20% depending on watershed size by utilization of what is termed the HOP Brook adjustment factor. Distribution of the total rainfall is made by the computer program using distribution methods developed by the Corps.

2. Inflow Hydrograph. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for reservoir routing.

The unit hydrograph is developed using the Snyder method. This method requires calculation of several key parameters. The following list gives these parameters their definition and how they were obtained for these analysis.

Parameter	Definition	Where Obtained
Ct	Coefficient representing variations of watershed	From Corps of Engineers*
L	Length of main stream channel miles	From U.S.G.S. 7.5 minute topographic
Lca	Length on main stream to centroid of watershed	From U.S.G.S. 7.5 minute topographic
Cp	Peaking coefficient	From Corps of Engineers*
A	Watershed size	From U.S.G.S. 7.5 minute topographic

\*Developed by the Corps of Engineers on a regional basis for Pennsylvania.

3. Routing. Reservoir routing is accomplished by using Modified Plus routing techniques where the flood hydrograph is routed through reservoir storage. Hydraulic capacities of the outlet works, spillways and the crest of the dam are used as outlet controls in the routing.

The hydraulic capacity of the outlet works can either be calculated and input or sufficient dimensions input and the program will calculate an elevation discharge relationship.

Storage in the pool area is defined by an area - elevation relationship from which the computer calculates storage. Surface areas are either planimeted from available mapping or U.S.G.S. 7.5 minute series topographic maps or taken from reasonably accurate design data.

4. Dam Overtopping. Using given percentages of the PMF the computer program will calculate the percentage of the PMF which can be controlled by the reservoir and spillway without the dam overtopping.

5. Dam Breach and Downstream Routing. The computer program is equipped to determine the increase in downstream flooding due to failure of the dam caused by overtopping. This is accomplished by routing both the pre-failure peak flow and the peak flow through the breach (calculated by the computer with given input assumptions) at a given point in time and determining the water depth in the downstream channel. Channel cross-sections taken from U.S.G.S. 7.5 minute topographic maps were used in the downstream flood wave routing. Pre and post failure water depths are calculated at locations where cross-sections are input.

# HYDROLOGY AND HYDRAULICS ANALYSIS DATA BASE

NAME OF DAM: Hidden Lake Dam

PROBABLE MAXIMUM PRECIPITATION (PMP) =  $22.2 (0.99) = 21.98''$

STATION	1	2	3
Station Description	Hidden Lake		
Drainage Area (square miles)	0.36		
Cumulative Drainage Area (square miles)	0.36		
Adjustment of PMF for Drainage Area (%) <sup>(1)</sup>			
6 hours	117		
12 hours	127		
24 hours	136		
48 hours	142		
72 hours	145		
Snyder Hydrograph Parameters			
Zone <sup>(2)</sup>	13		
C <sub>p</sub> <sup>(3)</sup>	0.5		
C <sub>t</sub> <sup>(3)</sup>	1.85		
L (miles) <sup>(4)</sup>	0.66		
L <sub>ca</sub> (miles) <sup>(4)</sup>	0.38		
t <sub>p</sub> = C <sub>t</sub> (LxL <sub>ca</sub> ) <sup>0.3 hrs.</sup>	1.22		
Spillway Data			
Crest Length (ft)	35		
Freeboard (ft)	0.2		
Discharge Coefficient	3.2		
Exponent	1.5		

(1) Hydrometeorological Report 40 (Figure 1), U.S. Army Corps of Engineers, 1965.

(2) Hydrological zone defined by Corps of Engineers, Baltimore District, for determining Snyder's coefficients (C<sub>p</sub> and C<sub>t</sub>).

(3) Snyder's Coefficients.

(4) L=Length of longest water course from outlet to basin divide.  
L<sub>ca</sub>=Length of water course from outlet to point opposite the centroid of drainage area.

CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: D.A. 0.36 mi<sup>2</sup> wooded, moderate slopes

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 82 ac-ft

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 87 ac-ft

ELEVATION MAXIMUM DESIGN POOL: Unknown

ELEVATION TOP DAM: 1000.2

SPILLWAY CREST:

a. Elevation	<u>1000.0</u>
b. Type	<u>Open cut shale</u>
c. Width	<u>35 feet</u>
d. Length	<u>Not applicable</u>
e. Location Spillover	<u>Right abutment</u>
f. Number and Type of Gates	<u>None</u>

OUTLET WORKS:

a. Type	<u>Entrance inverts 15" CMP</u>
b. Location	<u>Through embankment</u>
c. Entrance inverts	<u>Unknown</u>
d. Exit inverts	<u>980.2</u>
e. Emergency draindown facilities	<u>None</u>

HYDROMETEOROLOGICAL GAUGES:

a. Type	<u>None</u>
b. Location	<u>None</u>
c. Records	<u>None</u>

MAXIMUM NON-DAMAGING DISCHARGE: Unknown



L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS  
EBENSBURG PENNSYLVANIA

DAM NAME HIDDEN LAKE  
I.D. NUMBER DER. 110. 40-228

SHEET NO. 1 OF 4  
BY BJR DATE 6/19/80

### LOSS RATE AND BASE FLOW PARAMETERS

As recommended by the Baltimore  
District Corps of Engineers.

$$STRTL = 1 \text{ inch}$$

$$CRISTL = 0.05 \text{ in/hr}$$

$$STRTO = 1.5 \text{ CFS/mi}^2$$

$$QRCSN = 0.05 \text{ (5\% of Peak flow)}$$

$$RTIOR = 2.0$$

### ELEVATION - CAPACITY RELATIONSHIPS

Obtained from U.S.G.S. 7.5-MIN Quad  
and field inspection data

$$\text{Spillway Crest Elevation} = 1000.0 \text{ FT}$$

$$\text{INITIAL Storage} = 82.2 \text{ AC-FT}$$

$$\text{Top of Dam Elevation} = 1000.2 \text{ FT}$$

$$\text{Storage at Elevation } 1000.2 = 87.0 \text{ AC-FT}$$

$$\text{Zero Storage Elevation} = 985.6 \text{ FT}$$




L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS  
EBensburg PENNSYLVANIA

DAM NAME HIDDEN LAKE

I.D. NUMBER DEE. LD. 40-228

SHEET NO. 2 OF 4

BY AP DATE 6/9/60





L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS  
EBENSBURG PENNSYLVANIA


DAM NAME HIDDEN LAKE  
I.D. NUMBER DER. 110. 10-228

SHEET NO. 3 OF 4  
BY E.P. DATE 6/10/80

### DISCHARGE RATING CURVE

Determined by (HEC-1).

Assume Standard Weir Flow  
(N.T.S.)



Spillway Crest Elevation = 1000.0 FT  
Weir Length = 35 FT  
Coefficient of Discharge = 3.2

### OVERTOP PARAMETERS

Top of Dam Elevation (Low spot) = 1000.2 FT  
Length of Dam (Excluding Spillway) = 500.0 FT  
Coefficient of Discharge = 3.1  
 $\Delta L_{max} = 562.0$  FT  
 $\Delta V_{max} = 1005.7$  FT




L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS  
EBensburg PENNSYLVANIA

DAM NAME HIDDEN LAKE  
I.D. NUMBER DER. NO. 40-228

SHEET NO. 4 OF 4  
BY R.B. DATE 6/10/80

### DAM BREACH PARAMETERS

(N.T.S.)



RATIO of PMF (ETIO) = 0.05  
Side Slope of Breach (z) = 0.5  
Failure Time (TFAIL) = 1 hr.  
Depth of Overtop = 0.2 FT or 2.4 inches

### CHANNEL ROUTING

Channel Routing cross sections obtained  
from U.S.G.S. 7.5-MIN Quad.

Channel Manning's  $n$  (QN 2) = 0.05  
Overbank Manning's  $n$  (QN 1) = 0.06



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*

1 A1 ANALYSIS OF DAM OVERTOPPING USING RATIOS OF PMF  
 2 A2 HYDROLOGIC-HYDRAULIC ANALYSIS OF SAFETY OF HIDDEN LAKE DAM  
 3 A3 RATIOS OF PMF ROUTED THROUGH THE RESERVOIR (PA 1136)

4	B	268	0	15	0	0	0	0	0	0
5	B1	5	1	7	1	1	1	1	1	1
6	J	0.05	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8
7	K	0	1	1	1	1	1	1	1	1
8	K1	INFLOW	1	1	1	1	1	1	1	1
9	M	1	1	1	1	1	1	1	1	1
10	P	21.98	117	127	136	142	145	145	145	145
11	T	1.22	0.50	2.0	2.0	2.0	2.0	2.0	2.0	2.0
12	X	-1.5	-0.05	2.0	2.0	2.0	2.0	2.0	2.0	2.0
13	K	1	2	2	2	2	2	2	2	2
14	K1	ROUTE	1	1	1	1	1	1	1	1
15	V	1	1	1	1	1	1	1	1	1
16	V1	1	1	1	1	1	1	1	1	1
17	S5	0	0.2	2.0	6.5	17.2	32.1	51.2	76.4	82.2
18	S5	124.0	169.0	218.0	273.0	334.0	395.6	457.2	518.8	580.4
19	S5	985.6	987.6	989.7	991.6	993.6	995.6	997.6	999.6	1000.0
20	S5	1002.0	1004.0	1006.0	1008.0	1010.0	1012.0	1014.0	1016.0	1018.0
21	S5	1000.0	35.0	3.2	1.5	1.5	1.5	1.5	1.5	1.5
22	S5	1000.2	3.1	1.5	500.0	513.0	526.0	539.0	552.0	565.0
23	S5	10.0	177.0	485.0	513.0	532.0	549.0	562.0	575.0	588.0
24	S5	1000.2	1001.0	1002.0	1003.0	1004.0	1005.0	1005.0	1005.0	1005.0
25	S5	99	99	99	99	99	99	99	99	99
26	K	99	99	99	99	99	99	99	99	99
27	K	99	99	99	99	99	99	99	99	99

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1976  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*

RUN DATE= 80/06/12.  
 TIME= 07.59.20.

ANALYSIS OF DAM OVERTOPPING USING RATIOS OF PMF  
 HYDROLOGIC-HYDRAULIC ANALYSIS OF SAFETY OF HIDDEN LAKE DAM  
 RATIOS OF PMF ROUTED THROUGH THE RESERVOIR

NO	NHR	NMIN	IDAY	JOB SPECIFICATION				IPLT	IPRT	NSTAN
				IMN	IMIN	METRC	TRACE			
288	0	15	0	0	0	0	0	0	0	0
			JOPER	NWT	LROPT	TRACE				
			5	0	0	0				

MULTI-PLAN ANALYSES TO BE PERFORMED

RTIOS= .05 .10 .20 .30 .40 .50 1.00  
 NPLAN= 1 ARTIO= 7 LRTIO= 1

SUB-AREA RUNOFF COMPUTATION

INFLOW

ISTAQ	ICUMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

INVDG	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	.36	0.00	.36	0.00	0.000	0	1	0

PRECIP DATA

SPFE	PMS	H6	H12	R24	R48	R72	R96
0.00	21.96	117.00	127.00	136.00	142.00	145.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LROPT	STHR	ULTR	RTIOL	FRAIN	STHKS	RTIOK	STRTI	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.05	0.00	0.00

3/4

UNIT HYDROGRAPH DATA  
TP= 1.22 CP= .50 NTA= 0

RECESSION DATA  
SIRTO= -1.50 ORCSN= -.05 RTIOR= 2.00  
APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 5.35 AND R= 6.49 INTERVALS

UNIT HYDROGRAPH 38 END-OF-PERIOD ORDINATES, LAG= 1.23 HOURS, CP= .50 VOL= 1.00

8.	28.	35.	81.	95.	93.	70.	60.	51.
44.	38.	32.	28.	24.	20.	17.	15.	11.

4/0

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

# HYDROGRAPH ROUTING

## ROUTE

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
2	1	0	0	0	0	1	0	0
ROUTING DATA								
QLOSS	CLOSS	AVG	INES	ISAME	IOP1	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	

NSTPS	NSTD1	LAG	AMSK	X	TSK	STOKA	ISPRAT
1	0	0	0.000	0.000	0.000	-1000.	0

CAPACITY=	0.	0.	2.	7.	17.	32.	51.	76.	82.	87.
	124.	169.	218.	273.	334.					

D-12

ELEVATION=	986.	988.	990.	992.	994.	996.	998.	1000.	1000.	1000.
	1002.	1004.	1006.	1008.	1010.					

CRCL	SPWID	CUOM	EXPW	ELEV	COOL	CAREA	EXPL
1000.0	35.0	3.2	1.5	0.0	0.0	0.0	0.0

DAM DATA			
10PCL	COOD	EXPD	DAMWID
1000.2	3.1	1.5	500.

CREST LENGTH	10.	177.	485.	513.	532.	549.	562.
AT OR BELOW							
ELEVATION	1000.2	1001.0	1002.0	1003.0	1004.0	1005.0	1005.7

5/1

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7
RATIOS APPLIED TO FLOWS										
HYDROGRAPH AT	1	.36	1	.05	.10	.20	.30	.40	.50	1.00
		.931		53	105	211	316	421	527	1054
			1	1.4911	2.9811	5.9711	8.9511	11.9311	14.9211	29.8411
ROUTED TO	2	.36	1	.36	.86	.192	.298	.406	.512	1045
		.931		1.0211	2.4511	5.4411	8.4411	11.4911	14.5011	29.5811

D-13

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....										
ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM				
STORAGE		1000.00		1000.00		1000.20				
OUTFLOW		82		82		82				
		0.		0.		10.				
RATIO OF PHF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS			
.05	1000.40	.20	91.	36.	8.00	42.50	0.00			
.10	1000.61	.41	95.	86.	11.00	42.00	0.00			
.20	1000.86	.66	101.	192.	14.25	41.50	0.00			
.30	1001.04	.84	104.	298.	16.75	41.25	0.00			
.40	1001.18	.98	107.	406.	19.25	41.25	0.00			
.50	1001.29	1.09	109.	512.	21.00	41.25	0.00			
1.00	1001.70	1.50	118.	1045.	25.25	41.00	0.00			

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*

A1 RATIOS OF PMF ROUTED THROUGH THE RESERVOIR AND DOWNSTREAM  
 A2 DOWNSTREAM CONDITION DUE TO OVERTOP "HIDDEN LAKE DAM" - DER 90-228  
 A3 PLAN 1 ASSUMES BREACH. PLAN 2 ASSUMES NO BREACH.  
 B 288 15 0  
 B1 5  
 J1 0.05 1 1  
 K 0 INFLOW 1  
 K1 1  
 M 1 0.84 1  
 P 1 21.98 117 127 136 142 145 1.0 0.05  
 T 1  
 W 1.22 0.90  
 X -103 -0.05 2.0  
 K1 1 ROUTE 2  
 Y 1  
 V1 1 1 1  
 V2 0 0.2 2.0 6.5 17.2 32.1 51.2 76.4 82.2 87.0  
 V3 124.0 169.0 218.0 273.0 324.0  
 V4 985.6 987.6 989.7 991.6 993.6 995.6 997.6 999.6 1000.0 1000.2  
 V5 1002.0 1004.0 1006.0 1008.0 1010.0  
 V6 1000.0 35.0 3.2 1.5  
 V7 1000.2 3.1 1.5 500.0  
 V8 10.0 177.0 485.0 513.0 832.0 549.0 562.0  
 V9 1000.2 1001.0 1002.0 1003.0 1004.0 1005.0 1005.7  
 V10 20 0.5 980.2 1 1000 1000.4  
 V11 20 0.5 980.2 1 1000 1002.0  
 K 1 CHANNEL ROUTING  
 Y 1 1  
 V1 1  
 V2 0.06 0.05 0.06 938 960 1450 0.028  
 V3 0 960 50 950 100 940 102 938 107 938  
 V4 109 940 150 950 200 960  
 K 99

D-14

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HLC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*

RUN DATE\* 80/06/16.  
 TIME\* 05.31.42.

RATIOS OF PMF ROUTED THROUGH THE RESERVOIR AND DOWNSTREAM  
 DOWNSTREAM CONDITION DUE TO OVERTOP HIDDEN LAKE DAM - DER 40-228  
 PLAN 1 ASSUMES BREACH. PLAN 2 ASSUMES NO BREACH.

JOB SPECIFICATION									
NO	NHR	NMIN	IDAY	IMR	IMIN	METRC	IPLT	IPRT	NSTAN
288	0	15	0	0	0	0	0	0	0
JOPER				NWT	LROPT	TRACE			
				5	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN=2 NRATIO=1 LRATIO=1

RTIOS= .05

SUB-AREA KUNOFF COMPUTATION

INFLOW

ISTAO	ICOMP	RECON	ITAPE	JPLT	JPRT	JNAME	JSTAGE	TAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

THYDQ	TUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	TSNOW	TSAME	LOCAL
1	1	.36	0.00	.36	0.00	0.000	0	1	0

PRECIP DATA

SPEE	PMS	R6	R12	R24	R48	R72	R96
0.00	21.98	117.00	127.00	136.00	142.00	145.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LROPT	STNCR	DLTR	RTIOL	ERAIN	STKS	RTICK	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA

TP= 1.22 CP= .50 NIA= 0

RECESSION DATA

STRTU= -1.50 ORCSN= -.05 RTIOR= 2.00  
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN Snyder CP AND TP ARE TC= 5.35 AND R= 6.49 INTERVALS

UNIT HYDROGRAPH 3R FID-OF-PERIOD ORDINATES, LAG= 1.23 HOURS, CP= .50 VOL= 1.00  

R.	28.	34.	44.	54.	64.	74.	84.	94.	104.	114.
44.	28.	34.	44.	54.	64.	74.	84.	94.	104.	114.
44.	28.	34.	44.	54.	64.	74.	84.	94.	104.	114.

PLAN 2 SAME AS PLAN 1

8/11

# HYDROGRAPH ROUTING

## ROUTE

1STAG 2 ICOMP 1 IECON 0 ITAPE 0 JPLT 0 JPRT 0 INAME 1 IASTG 0 IAUTO 0

ALL PLANS HAVE SAME ROUTING DATA

QLOSS 0.0 CLOSS 0.000 AVG 0.000 JRES 1 ISAME 1 IORT 0 IPMP 0 LSTR 0  
NSTPS 1 NSIDL 0 LAG 0 AMSKK 0 X TSK STORA 1SPRAT 0

CAPACITY= 0. 04 124. 169. 218. 273. 7. 17. 32. 51. 76. 82. 87.  
ELEVATION= 986. 988. 990. 992. 994. 996. 998. 1000. 1000. 1000. 1000. 1000.

CREL 1000.0 SPWID 35.0 COOM 3.2 EXPW 1.5 ELEV 0.0 COOL 0.0 CAREA 0.0 EXPL 0.0

DAM DATA  
TOPLL 1000.2 COOD 3.1 EXPD 1.5 DAMWID 500.

CREST LENGTH 10. 177. 485. 513. 532. 549. 562.  
AT OR BELOW

ELEVATION 1000.2 1001.0 1002.0 1003.0 1004.0 1005.0 1005.7

BRWID 20. Z ELRM 980.20 TPAIL 1.00 WSEL 1000.00 FATELL 1000.40  
DAM BREACH DATA

WARNING \*\*\* TOP OF DAM, BOTTOM OF BREACH, OR LOW-LEVEL OUTLET IS NOT WITHIN RANGE OF GIVEN ELEVATIONS IN STORAGE-ELEVATION

BOTTOM OF RESERVOIR ASSIGNED TO BE AT 985.60  
STORAGE-ELEVATION DATA WILL BE INTERPOLATED ABOVE ELEVATION 1010.00



9/

HYDROGRAPH ROUTING

## CHANNEL ROUTING

**ALL PLANS HAVE SAME**

## PLANS HAVE SOME ROUTING DATA

CROSS		AVG		TRES		TSAME		TOPT		TPMP		LSTR	
0.0	0.000	0.00		1		1		0		0		0	

# NORMAL DEPTH CHANNEL ROUTING

QNT1)	QNT2)	QNT3)	ELNVT	ELMAX	RLNTH	SEC
.0600	.0900	.0600	938.0	960.0	1450.	.02800

CROSS SECTION COORDINATES--STA•ELEV•STA•ELEV--ETC

RUSS SECTION COORDINATES--STA.,ELEV.,STA.,ELEV.--LIC					
0.00	960.00	50.00	950.00	100.00	940.00
109.00	940.00	150.00	950.00	200.00	960.00
				102.00	938.00
					107.00
					938.00

STORAGE	0.00	.24	1.24	2.30	3.78	5.66	7.94	10.63
ON D13.73								

[illegible]

	0.00	32.19	114.49	287.26	590.91	1064.38	1741.57	2653.43	3828.81
OUTFLOW									
.....	-5296.98								

041006.89	7077.91	9179.94	11645.04	14514.47	17813.78	21567.81	25800.78	30536.30	35797.48
-----------	---------	---------	----------	----------	----------	----------	----------	----------	----------

ON	948.42
STAGE	938.00
	939.16
	940.32
	941.47
	942.63
	943.79
	944.95
	946.11
	947.26

ON 960.60

10/11

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO	1
HYDROGRAPH AT					
	1	.36	1	53.	
		.93)		1.49)	
	2		2	53.	
				1.49)	
ROUTED TO					
	2	.36	1	1965.	
		.93)		55.63)	
	2		2	36.	
				1.02)	
ROUTED TO					
	3	.36	1	1962.	
		.93)		55.57)	
	2		2	36.	
				1.02)	

D-18

1. The first part of the document is a title page. It contains the title of the report, the author's name, and the date of the report. The title is "The Effect of the New Tax Law on the Investment Industry". The author is "John Doe". The date is "January 1, 1980".

2. The second part of the document is an executive summary. It provides a brief overview of the findings of the report. It states that the new tax law has had a significant impact on the investment industry, particularly in the area of capital gains. It also mentions that the report includes a detailed analysis of the impact of the new law on various types of investments.

3. The third part of the document is the main body of the report. It contains a detailed analysis of the impact of the new tax law on the investment industry. It discusses the various types of investments that are affected by the new law, such as stocks, bonds, and real estate. It also discusses the impact of the new law on the investment industry as a whole, including the impact on investment returns and the impact on the investment industry's ability to attract new investors.

4. The fourth part of the document is a conclusion. It summarizes the findings of the report and provides recommendations for the investment industry. It states that the new tax law has had a significant impact on the investment industry, and that the investment industry should take steps to adapt to the new law. It also recommends that the investment industry should continue to monitor the impact of the new law and should be prepared to make further adjustments as needed.

5. The fifth part of the document is a list of references. It lists the sources of information used in the report, including books, articles, and government documents. The references are listed in alphabetical order.

6. The sixth part of the document is an appendix. It contains additional information that is related to the report, such as a list of abbreviations and a list of symbols. The appendix is located at the end of the report.

PLAN 1 .....	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	STORAGE	1000.00	1000.00	1000.20
	OUTFLOW	82.	82.	87.
		0.	0.	10.

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.05	1000.40	20	91.	2003.	2.96	43.19	42.50

PLAN 2 .....	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	STORAGE	1000.00	1000.00	1000.20
		82.	82.	87.
	OUTFLOW	0.	0.	10.

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION	TIME OF	TIME OF
					OVER TOP HOURS	MAX OUTFLOW HOURS	FAILURE HOURS
.05	1000.40	.20	91.	36.	8.00	42350	0.00


PLAN 1 STATION 3

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.05	19626	965.2	43.25

	PLAN	2	STATION	3
	RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS

•05	36•	939•2	42•75
-----	-----	-------	-------

APPENDIX E  
DRAWINGS




APPENDIX F  
GEOLOGY

### General Geology

Hidden Lake Dam lies within the Appalachian Mountain Section of the Valley and Ridge Physiographic Province. This region is characterized by overturned and asymmetric folds, local shearing and large, low-angle thrust faults. The only faulting indicated in the area of the reservoir is about seven or eight miles away, both to the east and to the southwest.

The bedrock underlying the lake and dam is the Mississippian aged Pocono Group. This group consists mainly of sandstone with lesser amounts of conglomerate siltstone, shale and coal. The moderate to thick bedding is normally well developed. The regular and steeply dipping to vertical joints are also well developed. The rocks of the Pocono Group are very resistant to weathering and form an excellent foundation for heavy structures. The interstitial and secondary porosity give the rocks of this group a high effective porosity.



Geologic Map of The Area Around Hidden Lake And Shickshinny Lake



**Pocono Group**

*Pre-dominantly gray, hard, massive, cross-bedded conglomerate and sandstone with some shale, includes in the Appalachian Plateau, Burgoon, Shickshinny, Cuyahoga, Cuyahoga, Cuyahoga, and K top Formations. Includes part of Onondaga of M. L. Fuller in Potter and Tioga counties.*

Scale : 1:250,000



